


# Memorandum



**Date:** December 18, 2012

**To:** Jack Osterholt, Director  
Department of Regulatory and Economic Resources (RER)

**From:** Julie Balogh, Manager   
Airports & Contracts Section  
Environmental Monitoring and Restoration Division  
Department of Regulatory and Economic Resources (RER)

**Subject:** CSBE goal for E08-DERM-01 Project #E08-DERM-01-016R3-CEI, Source Removal, Monitoring Well Installation and Sampling for the North County Neighborhood Service Center, located at 3201 NW 207 ST, on behalf of the Miami-Dade Department of Community Action and Human Services (CAHS)

---

## SENT VIA EMAIL

This is a request for Review Committee (RC) approval of the proposed Community Small Business Enterprise (CSBE) goal in order to proceed with soil source removal, monitoring well installation and sampling under the E08-DERM-01 Professional Services Agreement for the Miami-Dade Department of Community Action and Human Services (CAHS), Project #E08-DERM-01-016R3-AMEC, Source Removal for the North County Neighborhood Service Center.

The subject project consists of the removal and disposal of approximately 128 tons of contaminated soil, and the installation and sampling of one ground water monitoring well. This contract, a work order originating from the E08-DERM-01 Professional Services Agreement, has been assigned to AMEC Environment & Infrastructure, Inc. (AMEC).

**The Department of Regulatory and Economic Resources (RER) staff has evaluated the project and recommends a 0.0% CSBE subcontractor goal for this project (please see attached Analysis for CSBE Goal Recommendation). The property is contaminated and therefore any excavation or removal work must be performed by personnel including subcontractors that are certified in accordance with OSHA standards in Hazardous Waste Operations and Emergency Response (HAZWOPER); a requirement that the selected excavation subcontractor meets. At this time, there do not seem to be any OSHA HAZWOPER certified excavation companies on the CSBE list. Therefore, RER requests an exemption from the requirement to utilize a CSBE subcontractor for this project. Otherwise, please advise on the availability of CSBE OSHA HAZWOPER certified excavation companies.**

Thank you for your attention to this matter. If additional information is required, please call Becky Varley, the project manager, or me at (305) 372-6700.

KM  
Attachments

**ANALYSIS FOR CSBE GOAL RECOMMENDATION**

Source Removal, Monitoring Well Installation and Sampling for the North County Neighborhood Service Center, located at 3201 NW 207 ST, on behalf of the Miami-Dade Department of Community Action and Human Services (CAHS)

**PROJECT TITLE:**

**PROJECT NUMBER:**

**E08-DERM-01-016R3-AMEC**

**DEPARTMENT:**

**Department of Community Action and Human Services (CAHS)**

**ESTIMATED COST OF CONSTRUCTION:**

**\$ 41,806.21**

**FUNDING SOURCE:**

**Miami-Dade County Department of Community Action and Human Services (CAHS)**

**DESCRIPTION OF PROJECT:**

**Project #E08-DERM-01-016R3-CEI, Source Removal for the North County Neighborhood Service Center consists of the removal and disposal of approximately 128 tons of contaminated soil, and the installation and sampling of one ground water monitoring well.**

**TASK DESCRIPTION**

	<b>ESTIMATED QUANTITY</b>	<b>UNITS</b>	<b>ESTIMATED COST</b>	<b>CSBE COSTS</b>	<b>CSBE %</b>
Eng/Planning/Mgmt/Oversight/Laboratory/Reporting	L.S.	L.S.	\$ 11,783.77	\$ -	0.00%
Equipment & Materials (source removal)	L.S.	L.S.	\$ 13,132.24	\$ -	0.00%
Labor (source removal)	L.S.	L.S.	\$ 8,300.00	\$ 8,300.00	19.85%
Labor (monitoring well)	L.S.	L.S.	\$ 1,622.50	\$ -	0.00%
Allowance	L.S.	L.S.	\$ 6,967.70	\$ -	0.00%
<b>TOTAL CONSTRUCTION</b>			<b>\$ 41,806.21</b>	<b>\$ 8,300.00</b>	<b>19.85%</b>

**DTA:**

The above location is not within a Designated Target Area.

**Project duration:**

Less than 30 days.

**CWP:**

Does not seem to be applicable due to project duration and cost.

  
Julie Balogh, Manager  
Airport & Contracts Section, RER

  
Date Submitted ~~to~~ RER